Firmware RAMOS Optima

FW version SP8465

Table of added and fixed features

1 Fixed features:

- When password checking is disabled the SNMP community is not verified
- Changing the threshold value of temperature does not send SNMP traps
- Relay action wording "until Ack" does not show in drop down list
- When the humidity is 0%, the sensor shows sensor error (We added a 5% margin before setting the sensor error state)